# Safety rules in force of the company: Železiarne Podbrezová a.s. for external contractor and other visits.

This presentation is the intellectual property of Železiarní Podbrezová a. s. Copying and distribution is prohibited.





### Content

I. General health and safety requirements,

II. Environmental Protection,

III. COVID-19 measures,

IV. Important telephone numbers.



- I. Enter the premises of the company under the influence of alcohol or other psychotropic substances is prohibited. It is also forbidden to bring alcoholic or other narcotic and psychotropic substances into the premises of the company. Upon request, everyone is obliged to undergo a breath test. The test rejection or the positive result of the test have effect in the immediate expulsion of the person from the premises of the company.
- II. Smoking is prohibited in the company premises. Smoking is allowed only in areas designated for this purpose and marked "SMOKING ROOM".



III. In the area, moving is allowed only on the sidewalks or along the left edge of the road. In the establishment or workshop, the routes are marked with white (yellow) bands. Do not shorten your journey through technological or mechanical equipment. When walking up stairs, transition benches, etc., hold on the railings or handles. Only stay at workplaces where you have been assigned a job. To arrive and leave the workplace, use only the paths designated by the supervisor of the work (employee of ŽP a.s.).



IV. When moving in production facilities, use personal protective equipment (safety helmet, work shoes, work clothes, etc.) in accordance with the appropriate mark (pictogram) on the front door and as needed for the performance of your professions, activities. When working at heights and above depths, use all personal protective equipment (safety helmet with four-point attachment, safety harness, connecting device with fall arrester).



- V. Parking of vehicles is only possible in places reserved for this purpose, which are marked with a traffic sign.
- VI. Keep max. speed limit 20 km / h, traffic regulations and signs. Pay special attention to railway crossings. Stop the vehicle only 15 m and more in front of and behind the railway crossing.



VII. Perform only such activities for which you have professional (certificate, license, document) and medical competence (welding, flame cutting, work at heights, operation of VTZ, VZV, etc.).

VIII.Use only safe tools and implements.



- IX. Perform activities only in accordance with approved safe working and technological procedures, instructions.
- X. Do not stay or pass under the suspended load on the lifting device (material, bundle of pipes, etc.).



- XI. Store material, tools, implements, devices etc. as well as machinery only for reserved areas and areas designated by the supervisor of the work (employee of ŽP a. s.).
- XII. Do not carry out work in the vicinity of electrical equipment and high voltage cables unless an "B certificate" has been issued by the responsible employer of the company (operator of the relevant electrical equipment).



XIII.Do not carry out work on workplaces and equipment with a risk of fire or explosion unless a permit has been issued to carry out activities with an increased risk of fire or explosion - "P - certificate".

XIV.Do not interfere with the equipment or the production process of the company.

XV. Do not stay near of moving, rotating or vibrating parts of machinery.



XVI.If there is an exchange of workers or additions to their status during the work, make an introduction to the general health and safety requirements via the ZP a. with. and this material. The head of the contractor's working group is obliged to inform the head of the work on the work (employee of ŽP a. S.), Who, through the manager of the given workplace, will perform for new, resp. acquainted employees with specific requirements, resp. specific health and safety hazards (in paper form).



XVII.Immediately report the occurrence of the accident through the head of the contractor 's working group, another employee or witness of the accident to the head of the work (employee of ŽP a. S.) And dispatching of the environment a. with. The reporting obligation also applies to other adverse and extraordinary events or safety incidents (near misses, near accidents and near misses).



# The environmental protection

- Maintain order and cleanliness in the workplace and environmental regulations.
- II. Waste, hazardous chemicals and mixtures must not come into contact with or enter the soil, groundwater, surface water or sewage system.



# The environmental protection

- III. Ensure that no harmful, disturbing or otherwise undesirable emissions of dust, gas, odor, noise occur in the workplace, either in the workplace or in its surroundings.
- IV. Separate the waste that is generated in the designated reception containers.




# The necessary measures to avoid COVID-19

I. Observe and follow the current anti-pandemic measures in force at the time of the work agreed in the contract (current anti-pandemic measures issued by state administration bodies take precedence over the measures in the contract).









### Important phone numbers

I. Dispatching ŽP a.s. (accident, unwanted event ..) ext. 4020

II. The company Fire Department ext. 2222

III. The company Security Services ext. 3333

<sup>\*</sup> NOTE: If using a private mobile phone, use the prefix: 048/645 ....., for example 048/645 4020



### Respect the principles of health and safety





### Principles of safety and environmental protection

Welcome to Železiarne Podbrezová a.s. please pay attention to the following information.

Entryinto the premises of Železiarne Podbrezová a.s. is only permitted by registeringat the respective security gate. Visitors including their vehicles are always security checked.

Observe the legal regulations as regards to the occupational health and safety policy and do not risk safety and health of other employees.



While walking through the production and dispatching facility you must use protection equipment (helmet, working footwearetc.) in accordance with the signs (pictograms) displayed at the entrance doors.



Please follow the marked paths within premises. The paths are marked with white lines in mills and workshops.



Do not walk under or approach a crane or a suspended load (tube bundle or other items).



Throughout ŽP a.s premises taking photos and video recordings is strictly forbidden unless approved by ŽP a.s. management.



No persons 18 are permitted to enter ŽP a.s. premises (including hitchhikers, children, etc.).



All motor vehicles entering the premises must be in a good condition (the vehicle must have a relevant technical, environmental and safety certificate). The vehicle loading area must not be damaged, dirty or contaminated by substances harmful to the environment.



Vehicle must only be parked in designated parking areas.





Observe speed limit of 20 km/h, traffic regulations and signs.



Please pay special attention to railway crossings. Stop your vehicle at least 15 meters before and behind railway crossings.



Place all rubbish in dedicated bins. Do not drop litter.



It is forbidden to handle oil and other operation liquids.



In case anaccidental oil or other hazardous substances discharge contact 048 6454020. The employee will provide means for cleaning it



Please do not interfere with the production and technological process, do not operate any machines and appliances. Keep clear and do not approach any moving, swinging and rotating parts of machines, appliances, conveyors, handling and utility vehicles etc.



In case of injury, fire or other extraordinary circumstances please contact plant emergency tel. 048 6454020 or the company fire brigade tel. 048 6452222.



Smoking is restricted in ŽP a.s. premises. Smoking is only permitted in designated smoking areas.

Alcohol and drugs are strictly forbidden. Anyone suspected of being under the influence of above will also be forbidden entry.

Every person shall be obligated to undergo a breath test if requested to do so; refusal to undergo the breath test or a positive result shall mean the immediate removal of the person from ZP a.s. premises.

### Important phone numbers:

Injury, accident: 048 645 4020 Fire brigade: 048 645 2222, 5222 ŽP security service: 048 645 3333

Good bye and thank you for your visit.

Good bye and mank you for your visit.



This presentation is the intellectual property of Železiarne Podbrezová a. s. Copying and distribution is prohibited.

18



Železiarne Podbrezová, a.s. Kolkáreň 35, 976 81 Podbrezová Slovenská republika

> admin@zelpo.sk www.oceloverury.sk